



**PART - C (6 × 11 = 66 Marks)**

Answer ALL Questions

23. a) Derive the Townsend's first ionization coefficient and second ionization coefficient and obtain the criterion for breakdown. 11 K3 CO1

**OR**

- b) What are the causes for switching and power frequency over voltages? How are they controlled in power system? 11 K3 CO1

24. a) Explain the break down mechanisms of Cavitations & Bubble mechanism and Thermal mechanism of break down in commercial liquid dielectrics. 11 K2 CO2

**OR**

- b) Outline the various mechanisms of vacuum break down. 11 K2 CO2

25. a) Explain the different schemes for cascade connection of transformer for producing very high A.C voltages. 11 K2 CO3

**OR**

- b) Describe with a neat sketch the working of a Van De Graff generator. What are the factors that limit the maximum voltage obtained? 11 K2 CO3

26. a) Describe the generating voltmeter used for measuring high A.C voltages. 11 K2 CO4

**OR**

- b) Explain with neat diagram the principle of operation of an electrostatic voltmeter. 11 K2 CO4

27. a) With suitable diagram, explain the process of electrostatic precipitation. 11 K2 CO5

**OR**

- b) Discuss the role of High voltage engineering in electrostatic spinning. 11 K2 CO5

28. a) Explain the method of impulse testing of high voltage Transformers. 11 K2 CO4

**OR**

- b) Summarise the construction, principle of operation of a Generating voltmeter and give its applications and limitations. 11 K2 CO4